

Lisa 1.

Lisand	Tähis	Katse-keha nr.	Prao nr.	7-päevaselt tekitatud pragude sildamise protokoll												Sulgunud prao laius, mm		
				8 päeva	13 päeva	22 päeva	32 päeva	39 päeva	46 päeva	54 päeva	61 päeva	67 päeva	74 päeva	81 päeva	89 päeva	kuni 0,2	0,2-0,3	0,3-0,4
Etalon	E	1	E-1															
			E-2															
			E-3															
		2	E-4				+		+			+				.	.	.
			E-5						+	+						.	.	
			E-6		+			+	+							.	.	
		3	E-7	+	+		+	+			+					.	.	.
			E-8	+	+		+	+	+							.	.	.
			E-9					+	+							.	.	.
Penetron	E+1	1	E+1-1	+					+				+			.	.	
			E+1-2				+	+	+	+						.	.	.
			E+1-3						+		+					.	.	
		2	E+1-4					+	+	+						.	.	.
			E+1-5								+					.	.	.
			E+1-6		+				+	+						.	.	.
		3	E+1-7	+	+			+	+	+						.	.	.
			E+1-8		+		+		+							.	.	
			E+1-9		+	+	+		+							.	.	.
Xypex	E+2	1	E+2-1				+	+	+	+						.	.	.
			E+2-2															
			E+2-3		+	+	+	+	+							.	.	.
		2	E+2-4															
			E+2-5		+	+		+	+	+	+					.	.	.
			E+2-6			+							+			.	.	.
		3	E+2-7	+		+		+	+							.	.	.
			E+2-8	+	+			+	+	+						.	.	.
			E+2-9		+		+	+								.	.	.
Betocrete	E+3	1	E+3-1		+			+	+		+					.	.	.
			E+3-2	+				+					+			.	.	
			E+3-3		+		+		+		+			+		.	.	
		2	E+3-4	+	+			+	+	+						.	.	.
			E+3-5				+		+	+	+					.	.	.
			E+3-6										+			.	.	.
		3	E+3-7								+					.	.	
			E+3-8				+	+		+					+	.		
			E+3-9						+			+				.	.	.

Märkused.

Jrk. nr.	Tähis	Selgitus
1.	+	Praos on toimunud kinnikasvamist
2.		Pragu sulgus täielikult
3.		Avanenud pragu
4.		Ebaõnnestunud või halvima tulemusega pragu, mida ei arvestatud tulemuste analüüsimisel
5.		Betooni ankru polt purunes prao tekitamisel