

Lisa 2.

Lisand	Tähis	Katse- keha nr.	Prao nr.	28-päevaselt tekitatud pragude sildamise protokoll											
				14 päeva	21 päeva	29 päeva	36 päeva	42 päeva	49 päeva	56 päeva	64 päeva		71 päeva	78 päeva	85 päeva
				Tsoon A	-	Tsoon B	Tsoon A	Tsoon A	Tsoon A	Tsoon A	Tsoon A	Tsoon C	Tsoon A	Tsoon A	Tsoon A
Etalon	E	4	E-1												
			E-2												
			E-3						+						
		5	E-4	+							+		+		
			E-5												
			E-6											+	+
		6	E-7												
			E-8				+								+
			E-9	+				+			+				
Penetron	E+1	4	E+1-1												
			E+1-2											+	
			E+1-3									+			
		5	E+1-4												
			E+1-5												
			E+1-6	+		+				+	+				
		6	E+1-7												
			E+1-8												
			E+1-9	+											
Xypex	E+2	4	E+2-1												
			E+2-2												
			E+2-3												
		5	E+2-4												
			E+2-5												
			E+2-6												
		6	E+2-7												
			E+2-8												
			E+2-9												
Betocrete	E+3	4	E+3-1												
			E+3-2												
			E+3-3												
		5	E+3-4												
			E+3-5												+
			E+3-6										+		
		6	E+3-7												
			E+3-8												+
			E+3-9												

Märkused.

Jrk nr.	Tähis	Selgitus
1.	+	Praos on toimunud kinnikasvamist
2.		Pragu sulgus täielikult
3.		Vee läbijooks praost on peatunud
4.		Ebaõnnestunud või halvima tulemusega pragu, mida ei arvestatud tulemuste analüüsimisel

Jrk nr.	Tähis, tsoon	Selgitus, prao laius, mm
5.	A	kuni 0,2
6.	B	0,3 - 0,4
7.	C	0,4 ja rohkem